

- 15 **NEVER** allow lifting beams to strike the jib of the crane or any other obstruction when raising, lowering or transporting loads.
- 16 **NEVER** allow personnel to ride on loads.
- 17 Keep fingers, toes etc clear ensuring they do not become trapped when lifting, lowering and controlling loads.
- 18 Use tag lines to control long loads when necessary.
- 19 **ENSURE** that the beam remains at its intended attitude during use. Particular care must be taken when lifting and setting down as the load may become unstable or individual lift points may become overloaded.
- 20 **DO NOT** hammer, force or wedge lifting beam accessories into position; if they are the correct rated capacity (SWL) they will fit.
- 21 **DO NOT** expose beams to contact chemicals or high temperature unless they are supplied specifically for this purpose.
- 22 **DO NOT** attempt repairs. Contact the Hire Company.