

- 15 Vibration from the tool can cause '**VIBRATION WHITE FINGER**' and eventually other damage to hands and arms. Keep your hands warm at all times. Gloves can reduce vibration. If your hands start to feel numb, stop work and exercise your fingers to restore circulation. Limit your time using the tool as much as possible.
- 16 **CHECK** regularly that all ventilation grills or holes on motor housings are clear and free from dirt.
- 17 **DO NOT** use electrical tools in damp, wet or flammable conditions.
- 18 If the automatic cut-out operates, allow the motor to cool before re-starting.
- 19 **ENSURE** that the power pack is fully charge before the work commences.
- 20 **DO NOT** attempt repairs. Contact the Hire Company.